

# New Jersey Department of Transportation

## FY 2002 - 2003 Study and Development Program

ROUTE/PROGRAM	Project ID Numbers	
	DB No.	TIP No.

---

<b>23 94</b>	<b>7D 8C, Linwood Avenue to Walkill Avenue</b>	<b>8919</b>	<b>8919</b>
--------------	------------------------------------------------	-------------	-------------

**LOCATION/DESCRIPTION**

Route 23: South of Linwood Avenue to north of Walkill Avenue; Route 94: South of Orchard Street to Walkill Avenue, intersection improvements

It is proposed to realign and resurface Route 23 approximately approximately 0.2 miles from the intersection approaches to accommodate the addition of a dedicated left-turn lane in each direction. Route 94 will be realigned and resurfaced approximately 0.21 miles from the intersection approaches to upgrade the roadway width for standard travel lanes. Additionally, the existing intersection curb return radii will be increased to allow for unrestricted westbound turning movements. This project will be bicycle/pedestrian compatible.

SPONSOR: NJDOT

COUNTY: Sussex

MILEPOSTS: Rt 23: 35.37-35.56; Rt. 94: 35.51-35.71

STRUCTURE NO.: N/A

MPO	Phase	Year
NJTPA	FSD	2002

---

<b>94 CR 661</b>	<b>Beaver Run Road, Drainage</b>	<b>294J</b>	<b>294J</b>
------------------	----------------------------------	-------------	-------------

**LOCATION/DESCRIPTION**

Vicinity of Beaver Run Road, proposed drainage improvements

This proposed drainage improvement will alleviate drainage and icing problems in the northbound lane of Route 94. Proposed improvements may include cleaning and internal inspection of the 250-foot cross drain, repair broken sections of pipe and outle head wall, reconstruction of inlet headwall, construction of sub-surface drainage system with inlets along southbound shoulder.

SPONSOR: NJDOT

COUNTY: Sussex

MILEPOSTS: 34.56 - 34.63

STRUCTURE NO.: N/A

MPO	Phase	Year
NJTPA	FA	2002
NJTPA	FSD	2003

# New Jersey Department of Transportation

## FY 2002 - 2003 Study and Development Program

ROUTE/PROGRAM	Project ID Numbers	
	DB No.	TIP No.

---

<b>94</b>	<b>Hardyston/Vernon Township Drainage Improvement</b>	98399	98399
-----------	-----------------------------------------------------------	-------	-------

**LOCATION/DESCRIPTION**

This route is a two-lane roadway which experiences flooding conditions in the vicinity of Orts Road as well as Givans Road. In the vicinity of Orts Road the following is proposed: installation of drainage pipe along the southbound roadway; bicycle-safe grates; a detention basin; cut back of the slope and construction of a retaining wall to provide improved sight distance. In the vicinity of Givans Road the following is proposed: installation of drainage pipe along the northbound roadway; replacement of the existing undersized culvert.

SPONSOR: NJDOT

COUNTY: Sussex

MILEPOSTS: 36.60; 41.10 - 41.35

STRUCTURE NO.: N/A

MPO	Phase	Year
NJTPA	FSD	2002

---

<b>94</b>	<b>Warren/Sussex County, Bicycle Improvements</b>	97040	97040
-----------	-------------------------------------------------------	-------	-------

**LOCATION/DESCRIPTION**

Vicinity of Lincoln-Laurel Road to Route 206 (Newton), proposed bicycle improvements

The proposed project would eliminate gaps in a primarily bicycle compatible route, as well as provide signage/access to the Paulinskill Valley Trail which crosses Route 94.

The Paulinskill Valley Trail is a 26-mile trail, considered to have statewide significance.

Proposed intersection improvements at Route 206 and 94 will also be included.

SPONSOR: NJDOT

COUNTY: Sussex Warren

MILEPOSTS: 0 - 27.70

STRUCTURE NO.: N/A

MPO	Phase	Year
NJTPA	FA	2002
NJTPA	FSD	2003

# New Jersey Department of Transportation

## FY 2002 - 2003 Study and Development Program

ROUTE/PROGRAM	Project ID Numbers	
	DB No.	TIP No.

---

94	Yard's Creek	9371	9371
----	--------------	------	------

### LOCATION/DESCRIPTION

Bridge over Yard's Creek, proposed replacement

This project will provide for the proposed replacement of the existing bridge (Structure No. 2117-154), which is in overall poor condition due to the deterioration of the arch superstructure. Both haunch faces exhibit severe concrete disintegration and spalling with exposed rusted reinforcements.

SPONSOR: NJDOT

COUNTY: Warren

MILEPOSTS: 3.00 - 3.20

STRUCTURE NO.: 2117154

MPO	Phase	Year
NJTPA	FA	2002
NJTPA	FA	2003